ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0750	NA	ANASUYA CHANDRAPPA LAYOUT
Segment No.	**Total Length (m)**	
3/3-W0750/3110/09	229.92	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	229.92	77.546483	13.084169	77.546522	13.084738	M0000	W1297

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Intimation of work order to start work of modified estimate providing and asphalting to balance road and providing and laying pipeline in chitra layou	1000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Intimation of work order to start work of modified estimate providing and asphalting to balance road and providing and laying pipeline in chitra layout in attur ward no Yelahanka division, Yelahanka zone	003-15-000002
Work Order No.	**Work Order Date**	**Period of Extension**
BBMP/CE/YO/WO/81/2015-16	20/01/2016	30 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code ?**
28/01/2016	28/01/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked / Released (Rs)
B B UMESHA		0.00
Phone No.	**E-Mail ID**	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		PRADEEP
Date of Inspection	**Remarks**	
04/11/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	04/11/2016	04/12/2016	COMPLETED
SE	VASU K M	04/11/2016	04/12/2016	COMPLETED
EE	VASU K M	04/11/2016	04/12/2016	COMPLETED
AEE	ASHOK	04/11/2016	04/12/2016	COMPLETED
AE	PRADEEP	04/11/2016	04/12/2016	COMPLETED
AE	PRADEEP	04/11/2016	04/12/2016	COMPLETED

AE-03